#### REPORT DOCUMENTATION PAGE

AFRL-SR-BL-TR-99-

0107

mpleting	and	reviewing

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing in the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information. Occasions and Benort 1.215 inforces to ask timburs 2018 1.216 inforces to ask timburs 2018 1.216 inforces to the following the send of the collection of the collection of information.

ctorate for Information

Operations and Reports, 1215 Jefferson Davis Highway, Suite	2 1204, Arlington, VA 22202-4302, and to the Office of Man		group de poutus.
1. AGENCY USE ONLY (Leave blank)		3. REPORT TYPE ANO DA	
A TITLE AND QUATER'S	1 Mar 99	Final Technical	Report 15 Sep 95 to 14 Dec 98  15. FUNDING NUMBERS
4. TITLE AND SUBTITLE Fracture and Fatigue Crack Gr	owth Rehavior of Advanced C	'eramic Matrix	F49620-95-1-0500
Composites	own Behavior of Advanced C	cramic Mana	149020-93 1-0300
Composites			
6. AUTHOR(S)			
Dennis J. Buchanan			61103D
·			3484/WS
		<u> </u>	
7. PERFORMING ORGANIZATION NAME(S	3) ANO AOORESS(ES)		B. PERFORMING ORGANIZATION REPORT NUMBER
Structural Integrity Division Advanced Materials Characteri	izaitan Graun		1
University of Dayton Research	<u>=</u>		
300 College Park	mstitute		
_			
Dayton, OH 45469-0128  9. SPONSORING/MONITORING AGENCY N	IAME(S) ANO AODRESS(ES)		10. SPONSORING/MONITORING
AFOSR/NA			AGENCY REPORT NUMBER
801 N. Randolph Street, Rm 7	32		F49620-95-1-0500
Arlington, VA 22203-1977	•		1 47020-75-1-0500
11. SUPPLEMENTARY NOTES			
12a. OISTRIBUTION AVAILABILITY STATE			12b. DISTRIBUTION CODE
Approved for public release; d	istribution unlimited.		
13. ABSTRACT (Maximum 200 words)			
Ultrasonic C-scans have succes	sfully been used to investigate	damage from notches an	d holes in Nextel610/Aluminosilicate
(N610/AS) during tensile and f	fatigue loading conditions. Sec	ctioned fatigue specimens	verified that the region of distributed
matrix damage and longitudina	l fiber breakage correlated we	ell with the C-scan damag	e zone at 23°C. At 950°C the C-scan
			primarily due to self similar crack
-	<del>-</del>	-	the vicinity of the matrix crack. The
results from these tests are beir	ng employed to develop damag	ge and failure criteria for	N610/AS and other woven CMC.
	-	4 ^ ^	AA/49 A7A
		144	90412 079
		177	/UTIL UI/
14. SUBJECT TERMS			15. NUMBER OF PAGES
·			3
			16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	N 20. LIMITATION OF ABSTRACT
UNCLASSIFIED	UNCLASSIFIED	UNCLASSIFIE	

FRACTURE AND
FATIGUE CRACK
GROWTH BEHAVIOR OF
ADVANCED CERAMIC
MATRIX COMPOSITES

March 1999

D. Buchanan

# Fracture and Fatigue Crack Growth Behavior of Advanced Ceramic Matrix Composites

March 1999

Final Technical Progress Report

Grant No. F49620-95-1-0500

Prepared for:

AFOSR/NA Dr. Ozden Ochoa 801 N. Randolph St. Room 732 Arlington, VA 22203-1977

Prepared by:

Dennis J. Buchanan

STRUCTURAL INTEGRITY DIVISION Advanced Materials Characterization Group 300 College Park Dayton, OH 45469-0128

## Fracture and Fatigue Crack Growth Behavior of Advanced Ceramic Matrix Composites

#### <u>Abstract</u>

Ultrasonic C-scans have successfully been used to investigate damage from notches and holes in Nextel610/Aluminosilicate (N610/AS) during tensile and fatigue loading conditions. Sectioned fatigue specimens verified that the region of distributed matrix damage and longitudinal fiber breakage correlated well with the C-scan damage zone at 23°C. At 950°C the C-scan data showed that the damage zone was confined to the notch plane where damage was primarily due to self similar crack growth. Sectioned samples verified that longitudinal fiber breaks were predominant in the vicinity of the matrix crack. The results from these tests are being employed to develop damage and failure criteria for N610/AS and other woven CMC.

#### **Objectives**

The primary objective of this effort is to characterize the evolution of tensile, creep and fatigue damage in ceramic matrix composites (CMC) using nondestructive evaluation (NDE) techniques. The NDE measurements will also be correlated to results from conventional extensometry and damage/crack growth characterized using optical techniques.

#### Status of Effort

Ms. Victoria Kramb continued the investigation of damage progression from edge notches and center holes in a woven oxide/oxide, N610/AS, CMC system using ultrasonic C-scans. Specimens were C-scanned prior to testing and during interrupted fracture and fatigue crack growth (FCG) tests. Tests were conducted at 23 and 950°C. Interrupted FCG tests of edge notched specimens, showed that progressive damage, indicated by increasing crack mouth opening displacement (CMOD) and destructive evaluation, correlated with the ultrasonic C-scans. Fatigue cycling at an applied stress = 41 MPa at 23°C resulted in crack arrest. C-scans, taken during test interruption, showed no increase in the ultrasonic attenuation from the pretest condition. Cycling at applied stresses of 93 MPa at 23°C resulted in progressive damage as indicated in the C-scans that exhibited an increase in attenuation. At 23°C, damage was identified on sectioned specimens as distributed matrix cracking and longitudinal fiber breakage (Fig. 1a). The observed longitudinal fiber breaks were infrequent and widely distributed; however matrix degradation within transverse fiber tows was extensive. The size of the C-scan damage zone correlated well with the extent of matrix damage observed on the polished sections. At 950°C, progressive damage leading to eventual failure occurred for cycling at an applied stress = 41 MPa. A change in damage mode to self similar crack growth was observed at 950°C (Fig. 1b). The change in damage mode was reflected in the C-scans by a damage zone which was more confined to the notch plane than at 23°C. Sectioned specimens showed that longitudinal fiber breakage occurred along the entire matrix crack length. Extensive matrix cracking was observed only in the vicinity of broken longitudinal fibers. At 950°C, the C-scan damage zone was longer than the measured crack length. At both temperatures, the size of the C-scan damage zone was larger than that indicated by the exposed longitudinal fiber lengths on fracture surfaces.




Figure 1. Ultrasonic C-scans of edge notched fatigue cycled specimens and corresponding damage near the notch tip (a) 23 °C, 500,000 cycles at 93 MPa (b) 950 °C, 1,347,668 cycles at 41 MPa.

### **Accomplishments/New Findings**

### Research highlights and their significance to the field

Ultrasonic C-scans were used effectively to monitor damage progression from notches and holes in N610/AS subjected to tensile and cyclic loading conditions. The observed change in damage mode with temperature was correlated to changes in

ultrasonic attenuation at the notch tip. Under cyclic loading conditions, maximum applied loads that resulted in no progressive damage at room temperature resulted in fiber breakage and failure at 950°C. The C-scans reflected the change in damage mode. At 23°C, distributed matrix cracking resulted in a large damage zone, which was monitored using C-scans. Self similar crack growth at 950°C, resulted in failure at significantly lower stress levels than at 23°C. C-scans, of interrupted test specimens, were shown to be an effective method for monitoring crack growth under cyclic loading. The extent of damage above and below the crack plane was indicated during testing from C-scans and thus, measured stress redistribution around the notch tip. Comparison of the C-scan indicated damage zone with the damage zone size predicted using various failure models are being used in the development of a relevant failure criteria for N610/AS and other CMC systems.

#### **Personnel Supported**

Connection		-
1211	Lodostos	ı
	Redacted	1

Ms. Victoria Kramb, Materials Engineering Graduate Program, UD., Graduate Research Assistant (PhD), 6/96-Present. (33%)

**Inventions and Patents: None** 

**Honors/Awards:** None